Exhibit B



PERFORMANCE TRUCK



34211 Katy Freeway **BROOKSHIRE, TX 77423**

Main - (281) 239-7383 Service - (281) 239-7383 Fax - (281) 239-7383

Acct #

ROSEWOOD

12319 BATTLE RD

Bill-To

BEASLEY

V.I.N

R081014646:01 1XKDDB8X2BJ280055

R0810146461

COPY

Date

2/17/2024

Invoice

Year

2011

Make

KENWORTH

Model Owner T800

ROSEWOOD

(832) 306-7311

77417 (832) 306-7311

137268

Engine Model Engine Serial# Trans Model

Trans Serial #

Engine Hrs

Billing Type SR

Customer Unit #

Unit ID# Date In

Date In Service

Date Out

0 CASH Writer 2803

11/9/23

12/31/99

790,603

11/9/23

Terms

Customer PO#

Job#1 078-000 Condition

TRANSMISSION GETS STUCK IN NETURAL

GENERAL REPAIRS, MUDFLAPS, HANGERS - ALL LOCATIONS

Reviewer

2803

Correction

Cause

Customer states that truck wont come out of neutral. Drove inside shop, attempted to connect to the transmission, could not connect, made sure good can network at 120 ohm resistor, checks okay, made sure good resistance at the data link connector, made sure good connection at the engine side resistor, removed the transmission harness, made sure good can network, checks good, attempted to connect again, noticed that data link was spliced into, replacement of that portion of harness needed, was able to connect, found codes relating to the eca. checked power, checks okay, checked ground, checks okay, load tested system with high beam light, checks okay, shook harness, light never cut out, per steps replacement of eca needed. Went ahead and checked clutch life, clutch life is good but looks like system was never greased causing metal on metal contact, replacement of clutch needed per steps.

Replaced clutch with customers approval and inspected harness and oem connector, found that the harness had been spliced and damaged, found that the connector was damaged as well. replaced the harness and oem pluge, was able to power the unit up and keep trouble shooting, found the TCM has failed on the unit . informed the customer and gave his a updated quote. Waiting on customers approval.

Qŧ	y Jiem		Description			Binldl	Price	Extended *
- Internation			LABOR TO PERFORM RE	EPAIRS			(3,210.00
1	0810/SCR-423598844	8	MAG 1 TRANS HD 50V	W FULL SYN (1		PR27	157.17	157.17
2	081P/0411-240-2005		TOOL-REMOVAL, DEUTSCH, SIZE 20			\$801D	5.98	5,98
6	081P/0413-204-2005		PIN-CONNECTOR FIREWALL			SB01D	3.64	21.84
1	081P/K3985		KIT-HARNESS, TRANSMISSION			NOLOC	320.€7	320.67
1	081S/122002-35A		CLUTCH-ULTRASHIFTPLUS, 2 IN, 14			PR14	2,498.46	2,498.46
1	081P/6306LLUA1C3/2	E	BEARING	BEARING		DIS23	18,26	18.26
1	081P/K4252RX		KIT-ECA INCLINE			SB03	1,343.18	1,343.18
1	081P/173631-7		TERMINAL-FEMALE GOLD			SB01D	4.11	4.11
1	081P/281934-2		SEAL-ELECTRONIC AMP			SB31C	4.35	4.35
1	081P/K4252RX-CORE		KIT-ECA INCLINE			CORBIN	406.25	406.25
1	OGBURN		SUBLET TO OCGURN'S TRUCK				97.50	97.50
1	FRT		SHIPPING & HANDLING				0.00	0.00
	Total Labor	6,210.00	Total Parts	4,877.77	Total	11,087.77		

We are Hiring at this location for the following positions:

Submit your application at www.performancetruck.com Click Careers

Outside Parts Sales Service Technician **Truck Sales** Service Manager Mobile Service Tech **Parts Driver**

\\SYS-WEB\Forms\Service\Service Barcode Invoices\10_0_SVSLS_RO_OR.rot

Consolas 4/.90

Date Create: 11/9/2023 10:38:33AM

Date Update: 2/19/2024 9:24:53AM Time Printed; 2/19/2024 9:25:27AM

Page 1 of 2

ROSEWOOD

R0810146461 continued

Job#1 078-000 continued

l Oty Item	
l Oty ltem	Description Price Extended la
	Description Extended B
Approximate the second section of the second	



Ask Us about our Mobile Service Trucks We can assist on the **ROAD or at YOUR BUSINESS**



NOTICE OF WARRANTIES

Any warranties on the products sold hereby are those made by the manufacturer, if any. The seller hereby expressly disclaims all warranties either express are implied, including any implied warranty or merchantability or fitness for a particular purpose, and CLEVELAND MACK neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said product (s).

We hereby certify that these goods were produced in compliance with all applicable requirements of Sections 6, 7, and 12 of The Fair Labor Standards Act of 1938, as amended, and of regulations and orders of the Administrator or Wage and Hour Division issued under Section 14 thereof.

NOTICE PURSUANT TO SECTION 70,001, TEXAS PROPERTY CODE

I am the person or an agent acting on behalf of the person, who is obligated to pay for the repair of the motor vehicle subject to the repair contract. 1 understand that this vehicle is subject to repossession in accordance with 9.503 of the Texas Business and Commerce Code, if a check or money order for repair on the vehicle is stopped, distanared because of insufficient funds, no funds, or because the drawer or maker of the check or money order has no account or account on which it is drawn has closed.

SIGNATURE OF PERSON RESPONSIBLE OR FOR PERSON RESPONSIBLE

Signature here

6,210.00 Labor:

4,780.27 Parts: 0.00 Misc. Charges

0.00 Diagnostic: 97.50 Sublet:

250.00 Shop: 423.04

Please Remit Payment to: Taxes: 8.25 %

PERFORMANCE TRUCK Total: 1263 U.S. HWY 59 NORTH-CLEVELAND, TX 77328

11,760.81



Credit Card Accepted only when present at time of payment and with proper Identification documents



Jeld:

Please Print your name

\\SYS-WEB\Forms\Service\Service Barcode Invoices\10_0_SVSLS_RO_QR.rpt

Consolas 4/.90

Date Create: 11/9/2023 10:38:33AM Date Update: 2/19/2024 9:24:53AM

Time Printed: 2/19/2024 9:25:27AM

Page 2 of 2